

THE S AND X BAND RECORDINGS WERE EXTREMELY NOISY FOR THE FIRST PART OF MISSION. THE LEVEL OF THE 1 KC ON BOTH RECORDERS SHOULD BE RAISED. THE 3 KC SWITCHING TONE ON MASTER RECORDER WAS EXTREMELY WEAK. EXCEPT FOR USUAL COMMENTS ON COMMAND RECEIVER RECORDINGS, OTHER EQUIPMENT OPERATED SATISFACTORILY.

END OF MESSAGE